
ACCESSOIRES ACIER POUR CHAINES ET CABLES





08700 GESPUNSART

Tendeur 2 crochets électrozingués référence 0301

d	A	F	Р	LF	P en kg /100	Charge en daN dans l'axe (CMU)
6	82	40	8	125	8	32
8	95	52	10	180	15	58
10	115	60	12,5	207	27	104
12	140	68	16	245	46	160
14	158	82	16	288	72	200
16	178	95	21	320	100	220
18	200	110	22	365	140	240
20	218	115	24	390	200	260
22	235	125	27	420	255	320
24	250	130	30	440	320	350
27	285	150	32	515	480	440
30	320	175	36	610	665	460